

There can be different reasons for non-identification of substances

White reference

The white reference measurement is incorrect

1. Please check that the white reference measurement surface is clean and that the distance ring is fitted correctly.
2. Please re-run the white reference measurement.
3. If it is still not possible to obtain a correct measurement then please contact customer service.



If you have any questions, please contact your local distributor or us:



info@hiperscan.com or by telephone +49 351 212 496 0